

Recent Firmware Change History for Satlook G2/HD

// 8-12-2015 ----- smG2HD-204-EU -----

Fix Blink for G2HD-BW. Blink is now the same for both color and BW
Change battery percent calculation and battery therm BW missing lines
Reduce interrupt stack size to 0x100
Prevent Charging from briefly overwriting Complete when charging is finished
Digital - Tuning Menu sym rate and modulation not in right position
Eliminate possible WDT in RS232

// 30-11-2015 ----- smG2HD-203-EU -----

Allow alternate TFT color display usage
Remove function Transducer Check
Change Startup Screen
Correct EasyFind saving for AllSats
Restructured Rs232 section to prevent dropped chars

// 17-06-2013 ----- smG2HD-132-EU -----

Improve BER estimation for DVB-S2. Change to SNR relation described in user manual.

// 3-06-2013 ----- smG2HD-131-EU -----

Add LNB Type for C-Band with LO = 5.75 GHz

// 8-04-2013 ----- smG2HD-130-EU -----

Reduce time between DiSEqC bytes for Ellies Sat-CR LNB
Ensure 22kHz off after DiSEqC sent to Sat-CR LNB

// 12-3-2013 ----- smG2HD-129-EU -----

Add LNB Type for C-Band with LO = 5.95 GHz.

// 28-11-2012 ----- smG2HD-128-EU -----

Improve Spectrum Sweep sampling. Double sample for first sweep.
Update transponder list for "Check Transponder" function

// 13-05-2012 ----- smG2HD-127-EU -----

Change ChargePwm max and min to fix crash during charging on some units

// 25-04-2012 ----- smG2HD-126-EU -----

Simplify UniCable by having user select UserBand and IF Freq
Add DiSEqC command list to GoToX command
Change int.c to multiply knob turn more (change <3 to <5) for faster knob response

// 11-10-2011 ----- smG2HD-125-EU -----

Check for low battery voltage only when not charging
Remove serial number key check

// 27-03-2011 ----- smG2HD-124-EU -----

Increase length of battery symbol
Exp Power was not displayed on Digital Screen

// 7-03-2011 ----- smG2HD-123-EU -----

Backlight set to continuous goes off after 5 minutes. Fixed
EasyFind lock timeout and unlock timeout increased.

// 13-01-2011 ----- smG2HD-122-EU -----

Backlight timer not counting so backlight remains on. Fixed.

// 22-11-2010 ----- smG2HD-121 -----

Wrong CB after long lock and incorrect BER - Add check in demod